

383

TILLAMOOK COUNTY REWITNESS

D.V.I.F.

N.W. 1/4 COR. SEC. 10 T. 25 R. 9 W. E. WM.
S. E. DEC. #

10

See Map A-562 County Surveyor

HISTORICAL: W.E. Anderson set 2" IP in ± 1950's For This Corner in Relation To HG Stelzig Tract Survey
"Corner is Now Gone"

CONDITION

FOUND:


No Witness

COMMENTS: This corner set by using data from G.S. MAP # A-562 & existent 1/16 Cor to west & sec Cor to South of it

REWITNESS

202

1 SET 1/2" Iron Pipe ± 2" Below Surface from Map A562
4" x 4" x 48" Post N.W. EAST 19° feet
S. E.



NEW ACCESSORY:

PP # E4 206	24	S72°W	73' 9"	△
PP # 499-40R	24	N22-30°W	72' 25"	△

COMMENTS: This corner is in Driveway going Southerly off of Brickyard Loop Road

IN THE PRESENCE OF: G Arthur
S Skinner

DATE: 8-30-67

PHOTO #:

County Surveyor
Title
G.W.

County corner tag affixed.

TILLAMOOK COUNTY SURVEYOR

