


COPIED FROM ORIGINAL

TILLAMOOK COUNTY REWITNESS # 414



NEW MONUMENT SEC. 1/4 COR. 29 T 28 R 9 W., WM.
~~SEC.~~ ~~SEC.~~

HISTORICAL:

S3 128	A-710 J.L.C. PAT PISTACCHIO
S3 158	4-9 JACK GRAF TOLD ME OF
S3 438	THIS CORNER WE DUG IT OUT
S3 508	OF PAVEMENT FIRST TIME IN
10 67	A-1863 J.L.C. HOW MANY YEARS? J.L.C.


CONDITION FOUND: MONUMENT CASING WITH 2" IRON PIPE

Good	UNPLUGGED
	BK 10 Pg 67 1898 SET POST SW 29" N 28° 30' E 4.96 CHAINS

COMMENTS:

REWITNESS

I SET



"x	"x	" Post	N.W.	feet
" Hat Section		S. E.		
NEW ACCESSORY: PLUGGED IRON PIPE				
SET 56 NAILS				
Iron Pipe to 1				0.96 feet
Iron Pipe to 2				0.95 feet
Iron Pipe to 3				1.01 feet
Iron Pipe to 4				1.09 feet

COMMENTS: Casing is under ± 5" of Blacktop

IN THE PRESENCE OF: Gale Arthur
George Urrey

DATE: 12/10/69 PHOTO#: 7/13/78 J. J. Conlin, C.S.
 * = County corner tag affixed. TITLE