


TILLAMOOK COUNTY REWITNESS #420



SECTION COR. SEC. 31 32 T 2S R 9 W., WM.

HISTORICAL:
 MAP B-184 Partial Subdivision of section 31 | 32 259
 MAP A-241 (Vicinity Map)
 MAP B-499 JLE 1964 Partial Subdivision Sec 32 259
 MAP B-69 W.S. Coates & W.F. Anderson Subdivision section 6
 MAP F-41-100 D.H. Schrader 1909
 BK CT 10 Page 100 Book 1 Page 81 BK P17 Page 35
 FOUND: Book 4 Page 57


CONDITION

Good	Bridge Spike ± 10" Deep
(1971) Found telephone Pole S85°E 78.8 - still o.k. Book 4 Page 51	
(1971) Found telephone Pole S83°30'W 129.2 - still o.k. Book 4 Page 51	
(1971) Found Power Pole N74°W 59.42 - still o.k. (refer to back of this card)	
(1971) Found nothing of the old fence corner (N02°W ± 19 feet) (refer to back of card)	
(1971) Brass Cap is in same position.	

COMMENTS:

REWITNESS

1 SET 1 1/2" Iron Re-Bar with 3" Brass Cap & Cement
 "x" "x" "Post N. 1/2" North 12.69 feet
 96 " Hat Section



NEW ACCESSORY:

Power Pole #F26R8	N74°W 59.42	△ Hub Jack on West Side of Pole.
Old fence corner Post	N02°W @ ± 19 feet	(Now GANE 1971)

COMMENTS: Cap is located ± 6" north of east-west centerline stripe. This area is farm land north of the corner is an open field. Corner check (1971) GALE ARTHUR BOGAR KNIPPEL NO OTHER B.T.S WERE FOUND!

IN THE PRESENCE OF: ALLEN Ducan RS 793
 George Urrey
 Gale Arthur

DATE: January 1970 PHOTO: [unclear]
 County corner tag affixed. TITLE GWN