

TILLAMOOK COUNTY REWITNESS #462

17	16
20	21

SEC. COR. 17/16  
20/21 T 2 S R 10 W., WM.

HISTORICAL:

GLO	BK 2510	Pg 19	end 66
	Bk 10	Pg 111	
	Map A-774 and 782		
	Map A-1933		

CONDITION

FOUND:


Fd good (GLO)	36" Spruce Stamp, No scribing visible on old face bears S 59° E 194 ft. to face.
Fd good (GLO)	40" Hem. Stamp, No scribing visible on open rotted face bears N 66° E 112 ft. to face.
Fd bad to rusted	1 1/4" Iron Pipe (Map A-782) with a 3/4" I.P. with Brass Cap (Map A-1933). Driven inside of 1 1/4" I.P.

other two GLO trees are gone.

COMMENTS:

REWITNESS

1 SET A 1 1/2" x 30" IRON PIPE WITH A BRASS CAP  
Set in CONCRETE.



\* 60" Hat Section 15 South 4" x 4" white Post 08' W  
NEW ACCESSORY:

* 20" Dia. Hemlock	Bears N 12° W	64.25 ft. to face
Scribed "T 2 S R 10 W S 17 CS BT"		

COMMENTS: I removed the Iron Pipes and B.C. and set C.S.B.C. in place of.

The corner lies approx. 200 ft South of the end of Crown road # 1541

IN THE PRESENCE OF: TERRY JONES  
GALE ARTHUR

DATE: 6/11/81

MAP PHOTO #:

\* = County corner tag affixed.

TILLAMOOK COUNTY REWITNESS

TITLE