

USDA FOREST SERVICE GPO 940-117

Index File No. _____

CORNER RECORD (SEARCH) (Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. A-11

T 3S R. 9W R.D. HEBO County TILLA State ORE. #491

Merid. WILL N.F. SIUSLAW

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT ~~FOUND~~ LINCOLN WILKES, GLO 1896 SET CEDAR POST AND MARKED:
8" FIR, N. 79° W., 6 LKS.
12" FIR, S. 42° E., 13 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 1" PIPE 18" ABOVE GROUND ALONGSIDE A 4x4x30 HARD FIR LIMB POST WITH TIN MARKED 1/4 COR. MW-RA.
FOUND 18" ROTTED STUMP 24" HIGH, S. 42° E., 8 FT. WITH VISIBLE SCRIBE MARKS "BT".

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At: _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOUND 18" ROTTED STUMP N. 79° W., 4 FT. WITH MARKS ROTTED OFF.

PLANE COORDINATE POSITION DATA
 X _____
 Y _____
 Estab. By _____
 Agency _____

OVER FOR ADDITIONAL RE-WITNESS

Signature Leonard Whitmore Title Forestry Tech Division Junior Headquarters Hebo Date 4-3-64 State Registration No. 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I MARK 2 BT'S: Leonard Whitmore 11-20-69 Tilla, Co. Dep. Surveyor
9" Hemlock, growing over ORIGINAL SE BT STUMP, S. 39° E., 8 FT. TO NAIL
HEAD AT SCRIBED "B" ON FACE MARKED 1/4 S 4 BT CS.
28" SAWED OFF FIR STUMP 6 FT. HIGH, S. 15° W., 11 1/2 FT. MARKED 1/4 S 4 BT CS
1 FT. E.
SET ALUMINUM GUARD POST WITH PENALTY TO DESTROY TIN ATTACHED

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
C. WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENT
2/2/75 J. L. Cantel Co. Surveyor