

T2S R9W

TILLAMOOK COUNTY REWITNESS #493

DATE

32

SEC.

SECTION COR. 675 T 35 R 9 W., WM.

T3S R9W

T3S R9W

6

5

HISTORICAL:

MAP A-1152

MAP B-69

Book 5-3 Page 154

Book 5 Page 104


CONDITION Good FOUND: Bridge Spike @ ± 10" deep

| | |
|-------|--|
| FOUND | 40" Cedar Stump S3°30'E 83 ⁵ |
| FOUND | 36" Cedar Stump S26°30'E 91 ⁵ |
| | |
| | |

COMMENTS:

REWITNESS

1 SET 1/2 Iron Re-bar with 3 Brass Cap & Cement



LOCATION OF FOUND BRIDGE SPIKE SOUTH 96" Flat Section NORTH 1515 feet

| | | |
|-----------------------------------|-----------------------|-----------|
| NEW ACCESSORY: NEW BITS MADE 1974 | | |
| *18" SPRUCE | S03°E 84 ⁰ | 5.5 BT CS |
| *14" CEDAR | S32°E 96 ⁰ | 5.5 BT CS |

COMMENTS: Cap is located ± 6" South of East - West center line stripe. Cap flush with pavement. Old fence corner bears N02°W ± 19 feet.

IN THE PRESENCE OF: A. Duncan, G. Urey, G. Arthur

DATE: Jan. 1970

PHOTO

Handwritten signature and title area

* = County corner tag affixed.