

TILLAMOOK COUNTY REWITNESS # 498
 SEC. COR. $\frac{6}{718}$ T 35 R 9 W., WM.

HISTORICAL: G.L.O. Pg. 44 359 1880


BOOK	PAGE	MAPS
1	498	B-1075 A-2528
HAYS	103	B-1073 A-1152
		B-1074
		B-69

CONDITION DISTURBED FOUND, 2" IRON PIPE WITH 3" BRASS CAP

FD. SHATTERED REMAINS S 48° W. 23 LKS	12" HEMLOCK	S. 18° W. 23 LKS.	G. L. O. Pg. 44
NOT FD.	4" V. MAPLE	S. 35° E. 26 LKS.	G. L. O. Pg. 44
NOT FD.	4" V. MAPLE	N. 76° W. 16 LKS.	G. L. O. Pg. 44
FD. STUMP SHATTERED BY LOGGING	15" HEMLOCK	N. 45° E. 50 LKS.	G. L. O. Pg. 44
Now 37" STUMP 5' HIGH	27" FIR	S. 25° E. 56 1/2 LKS.	MICROFILM FICHE 70E7
Now 23" STUMP 5' HIGH	20" HEMLOCK	S. 51° W. 29 LKS.	" " "
Now Low CUT STUMP 2' HIGH	62" HEMLOCK	N. 30° W. 6 LKS.	" " "
COMMENTS: Now 31" STUMP	30" HEMLOCK	N. 22° E. 59 LKS.	" " "
10' HIGH SCRIBING SC VISIBLE FACES SE			

REWITNESS

1 SET CONCRETE CYLINDER AROUND FOUND 2" IRON PIPE WITH 3" BLM BRASS CAP.



* 60" Hat Section S. 6° E. 17 FEET

NEW ACCESSORY:

AREA IS NOW CLEAR CUT; NO TREES LEFT.		

COMMENTS: THIS CORNER IS LOCATED ± 300' SOUTH OF A GRAVEL LOGGING RD ± 300' WEST OF THE POWER LINES & ON THE SOUTH SIDE OF A SMALL RAVINE. FD. MONUMENT HAD BEEN DISTURBED BY CURRENT LOGGING OPERATION AND WAS CHECKED FOR VALIDITY BY FIELD TIES TO 1/4 COR. $\frac{6}{718}$ T35R9W AND 1/4 $\frac{6}{718}$ T35R9W AGAINST THE PRESENCE OF: AL DVORAK DAN McNUTT

RECENT TIES MAP B-1073, B-1074, B-1075

DATE: 2-5-85 PHOTO#: _____ TITLE _____

* = County corner tag affixed.