

TILLAMOOK COUNTY REWITNESS

#503

W. SEC. $\frac{1}{4}$ COR.

7 T 3 S R 9-10 W., WM.

HISTORICAL: GLO PAGE 6 SET 4' POST 6" DIAM 1882

BOOK	PAGE	BOOK	PAGE	MAPS
2	124-487	CT1	14	A-901
10	95	1	6	A-2528
S3	256	2	124	
CT17	39	4	10	
HAYS F	30			

CONDITION

FOUND: OSBF IRON PIPE WITH BRASS CAP

GCNE	2 1/2" ELDER	S52W 100 LKS	GLO PAGE 6
GCNE	3" ELDER	S16E 110 LKS	" " "
GCNE	30" FIR	N17E 83 LKS	
BAD FD	10" SPRUCE	S67W 16 LKS NOW	W23" ROTTED STUMP
BAD FD	16" HEM STUB	4 FEET HIGH	S20E 190
LIVE FD	17" FIR N30W	S35E NOW 24"	

COMMENTS:


LIVE FD 17" HEM S30 1/2 E 129 S
 FD 4X4 W.C. POST - LYING IN CREEK.
 FD 1/4" BOLT 3' LONG - N12W 17

REWITNESS

1 SET 10" TILE AROUND FD OSBF BRASS CAP AND FILLED WITH CONCRETE

"x "x " Post N.W. feet

84" Hat Section WEST 15



NEW ACCESSORY:

DO NOT CUT TAGS ON	LIVE BT'S	
YELLOW COX TAGS ON	LIVE BT'S	

COMMENTS: THIS CORNER IS LOCATED ALONGSIDE OF SMALL CREEK WHERE THE BANK HAS WASH AWAY. BY PERMISSION OF COUNTY SURVEYOR WE BUILT A RETAINING WALL AND RESET CORNER. USED 1/4" BOLT FOR B.O. WHICH IS S81W 8 3/4

IN THE PRESENCE OF: GALE ARTHUR - DAN MC NUTT

DATE: 2-74

PHOTO#:

* = County corner tag affixed.

TITLE