

TILLAMOOK COUNTY REWITNESS #546
 1/4 COR. 28/33 T 3 S R 9 W., WM.

HISTORICAL: G.L.O. 3 S 9 pg 31+32



Map B - 554	
BK. 1 pg 238	
BK S 3 pg 282	
Map A - 4423	

CONDITION	FOUND:
Ed. unstable	BLM BRASS CAP on IRON PIPE
	1/2" IRON PIPE alongside BLM Brass cap (Bk. 1 pg 238)
Ed. Fair 20' sag	41" Dia. bears S 56° W 11' 0" ft to visible scribing "1/4 S 33 RT" (GLO) (Bk 1 pg 238)
Ed. Good 30'	Dia. Fir with healed face bears N 64° E 10' 36" ft to bark. (Bk 1 pg 238)

COMMENTS:

REWITNESS

1 SET Two 1 1/2" x 30" IRON PIPES with BRASS CAPS SET IN CONCRETE.



RM 1 * 60" Hot Section 15' E
RM 2 * 60" Hot Section 15' S

COMMENTS: 1/4 Corner to RM 1 bears S 82-10-54 E 28.696 ft ; 1/4 Corner to RM 2 bears S 21-06-27 W 21.436 ft ; RM 1 to RM 2 bears S 66° W 39.57 ft
 NOTE: Basis of bearing is Hand compass from RM 1 to RM 2

IN THE PRESENCE OF: TERRY JONES
 See field notes in note bin 35928 2' E DIC GALE ARTHUR

DATE: 7/24/81 PHOTO# 9-9-1981
 TILLAMOOK COUNTY REWITNESS TITLE

* - County corner tag affixed.