

T.3 S. R.9 W. No. Z-3 Cor. 1/4 Mer. Will. State ^(Rectangular) ORG. N. F. Siuslaw Dist. HeBo

2. Corner Status

	31		

3. Original Description _____ Vol. _____ Page _____ Where Recorded #560

4. Description of Corners:

5. Investigation Notes:
 ORIGINAL CORNER IS GONE.
 FOUND 42 IN. FIR SNAG, S. 50° E., 54 LKS. (ORIG.) WITH
 VISIBLE MKS. 1/4 S BT.
 FOUND 60 IN. FIR SNAG, N. 31° E., 54 LKS. (ORIG.) WITH
 ALL MKS. ROTTED OFF.

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey
 Status _____

6. Signed M. WHITMARE Title DEP. SURVEYOR Date 8-9-62

PERPETUATION RECORD

10. Monument:

11. Accessories NEW BT'S
 40 IN. FIR, N. 66° 30' E., 94 LKS. MKC 1/4 S 31 BT } BOTH BT'S PERTAIN TO SEC. 31
 18 IN. ALDER, N. 69° W., 51 LKS. MKC 1/4 S 31 BT } ONLY

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) (City) (County) (State)

14. Remarks:
 AT POINT FOR CORNER I SET 3/4 IN. PIPE, 30 IN. ABOVE GROUND
 WITH A WOOD STAKE ALONGSIDE THE SAME HEIGHT.