

TILLAMOOK COUNTY REWITNESS #581

2 1
11 12

SECTION COR. SEC. 2-1
11 12 T 35 R 10 W., WM.

HISTORICAL MAPS

Book	Page
A-1008	10 31
A-901	53 256
A-685	1 89
B-69	1 11
	4 77
	2 394

CONDITION FOUND: 2" Iron Pipe @ ± 2^s below surface

GONE	30" Hem N27E	9 ²⁹	BK 10 Pg 31	1888
GONE	22" Hem N26W	36 ⁹⁵	BK 10 Pg 31	1888
GONE	20" Hem S22W	17 ¹⁶	BK 10 Pg 31	1888
GONE	80" Spr S10E	16 ⁵⁰	BK 10 Pg 31	1888
GONE	4" Hem N48E	9 ⁵	BK 4 Pg 77	1950
Found	10" Hem N27½W	39 ⁰	BK 9 Pg 77	1950
Found	10" Hem S030E	74 ⁺	BK 4 Pg 77	1950
COMMENTS: Found	21" Hem N35E	54 [±]	BK 2 Pg 394	1957
Found	17" Hem N01W	52 [±]	BK 2 Pg 394	1957

TURN OVER FOR MORE

REWITNESS

SET 2" Iron Pipe with Brass Cap over Found I.P.
set Brass Cap in 8" Tile & Cement

2 1
11 12
RS 287
1972

* 96 " Har Section NW 192
NEW ACCESSORY: Iron Pipe with Brass Cap is
now ± 3" below Road Surface.
Corner is in south track of road on
south edge of track.
Placed tags on "Found" Bearing Trees

COMMENTS

GONE	80" SPR S12E	16 ⁵	Page 14 GLO 1882
GONE	20" Hem S64W	25 ⁷⁴	GLO 1882
GONE	18" Hem N26W	36 ³⁰	GLO 1882
GONE	24" Hem N20E	9 ²⁰	GLO 1882

IN THE PRESENCE OF: Gale Arthur
Roger Knipple

DATE: 1-13-72 PHOTO: REC
TILLAMOOK COUNTY BEARINGS FILE GLO 72