

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 3 S. R. 10 W. Mer.
1/4 Corner common to Sections

10, and 15
Corner consists of a PIPE (not) in place

State condition

Dimensions above ground 1 1/2 Ft. inches
Sketch grooves, letters, figures, or notches, on proper face of edge.

CARDINAL POSITION

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Hem. Spr. Remains of old Hem. Stump
Diameter 3.6 ins. N.P.W.
Bearing S. 10° E. 12 Lks.
Distance 15 Lks.

Do you believe this to be a genuine Land Office Corner? Yes
If not why? The old cruiser mark X is very convincing.


Mervin Whitmore
(Signature)

6-14-54 Fire Control Aid
(Date) (Title)

#607

S 10
15
N 1/4 cor

Record
sius/gw



T. 3 S. R. 10 W. Will. Mer.
(Make sketch of topography near Corner and show section line markers thus "X")

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ (bearing) _____ (Distance) Chains.

Section line marker between Secs. _____ and _____ is on _____ (Tree, post, etc.) on the _____ (Name of road, trail, etc.) located _____ (Chains E. W., N. S. from Sec. Cor.; 1/4 Cor.; fillet Cor. (Cross out nonapplicable))

Give any further facts needed to find Corner again:
NEED WHITMORE WAS A DEPUTY COUNTY SUPERVISOR EMPLOYED TO BE WITNESSES POSITIVE EVIDENCE OF ORIGINAL AGREEMENTS

Stephen J. Conliffe