

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

Box File No. Z-19 R. LOW R.D. HEBE County TILLA CO # 647

Grid. MILL N.F. SIGSLAW State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLC 1879 SET A POST 4 M.D.:
40" FIR, N. 22° E., 30 LKS.
36" FIR, S. 4° E., 24 LKS.
A BROOK 4.50 CHS. E. RUNS SOUTH.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND REMNANTS OF ORIGINAL BT'S BOTH ARE NOW ROTTEN SNAGS WITH NO SCRIBING VISIBLE. THE POST IS NO LONGER APPARENT, BUT THE CORNER CHECKS WITH THE CALL DISTANCE TO THE BROOK.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
THE OLD BEARING TREES ARE NOW;
44" SNAG, N. 22° E., 19 1/2 FT.
65" SNAG, S. 4° E., 16 3/4 FT.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Taken At _____
 Subject Ident. _____
 Taken By _____
 Signature _____

PLANE COORDINATE POSITION DATA
 Zone _____
 Date _____
 Stationed By _____
 Agency _____

Division _____ Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
SET IRON POST WITH BRASSCAP MARKED;

1/4 Rivet
T35
S35
S2
1971
816

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
MARK 3 New BT'S:
35" FIR, N. 77 1/2° W., 18 1/4 FT. SCRIBED "BT 1/4 S 35"
15" ALDER, S. 32° E., 25 FT. SCRIBED "BT 1/4 S 2"
23" FIR, N. 79 1/2° E., 39 1/4 FT. SCRIBED "BT 1/4 S 35"
SET STEEL POST 6 FT. EAST OF THE CORNER.

Work Done By TIMBERLAND SERVICE Title ARLS Date 9-71 State Registration No. or Agency 816

Certified Cor. Record Prepared? Yes No Filed At: TILLA CO. COURTHOUSE Date 9-72

REMARKS