

1. T 4 S R 9 W No 13 P Cor. 1/4 Mer. Will State ^(Rectangular) ORE. N. F. S 705 1/2 W Dist. Hebo

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded #705

4. Description of Corners: post

5. Investigation Notes:
 Found original post marked 1/4 S 21 on W. and 1/4 S 22 on E. side, still standing in rock mound.
 The old bearing tree snags are in their proper bearing and distances but all scribbling is rotted away.

6. Signed L. Whitman Title Forestry aid Date 5-22-61

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey _____
 Land Status H.F.

PERPETUATION RECORD

10. Monuments
 The original post was in good enough state of preservation to re-use for corner post with a rock mound at its base.

11. Accessories new BTS
 2 in. fir S. 77° W., 3 1/2 ft. mhd. 1/4 S 21 BT
 1 1/4 in. forked top fir, N. 77° E., 13 1/2 ft. mhd. 1/4 S 22 BT

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) (City) (County) (State)

14. Remarks:
 Witnessed by Deputy Surveyor M. Whitman
 Witnessed by Bernie Sheehan
 5-11-1961