

**UPDATED 1976**

USDA FOREST SERVICE GPO 9-11-76

INDEX FILE NO. L-25 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. 1-25 Cor. No. 742

T. 4S R. 10W R.D. HEBO County TILLAMOOK

M. WILL N.F. SIUSLAW State ORE

**CORNER DIAGRAM**

**DESCRIBE CORNER MONUMENT FOUND**

GLC 1879 SET A CEDAR POST  
20" SNAG, N. 56° W., 11 LKS.  
48" SNAG, N. 56° E., 4 LKS.

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

FOUND 1 1/2" GALV. PIPE 4" ABOVE GROUND ALONGSIDE A 4x4x10" POST. 14 1/2 FT. TO FACE

FOUND A 30" FIR, N. 18° W., 15 FT. WITH A HEALED FACE. I CHOPPED OPEN AND FOUND MARKS "CS 1/4 S 13" R

FOUND 12" ALDER, N. 76° W., 4 1/2 FT. TO FACE

SET BY W. ANDERSON CS 1954 MAP A 578

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**

ABOUT 30 FT. TO THE S.W. IS THE ROTTED STUMP OF A SNAG. 2 1/2 FT. S. 46° W. AS IN RECORDS I FOUND 2x4x36 REMNANT OF CEDAR THAT MAY HAVE BEEN THE ORIG. POST. ABOUT 25 FT. SOUTH IS AN OLD SIDE BLAZE ON WEST SIDE OF SAID OFF SNAG. N. 56° W., 73 FT. IS ROTTED STUMP.

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
Signature \_\_\_\_\_

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Established By \_\_\_\_\_ Signature \_\_\_\_\_  
11718 DIVISION \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_  
Forestry Tech Timber Hebo 5-7-69 7100-52 (3-68)

SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ALUMINUM 3" TOP ON 2 1/2" X 28" ALUMINUM PIPE. MARKED AS SA 13

SET IRON FENCE POST 2 FT. NORTH AND ATTACH "ATTENTION" AND BOUNDARY SIGNS.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

THE BARK SCRIBES ON THE 12" ALDER, N. 76° W., 5 1/2 FT. ARE ILLEGIBLE. RE SCRIBE BELOW IN BARK "1/4 S 13 BT." DISTANCES ARE TO SIDECENTER

ANDERSONS OTHER BT IS 30" FIR, N. 17° W., 15 1/2 FT. VAR. 21°

This corner pertains to east boundary section 13 only.

Ken Byington, witness  
Leonard Whitmore, Tillamook Deputy County Surveyor 6-10-76

Work Done By L. Whitmore Title Tilla. Co. Dep. Surveyor 6-76 State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_


Certified Cor. Record Prepared?  Yes No Filed At: County Surveyors office Date 6-76

REMARKS

FOUND PIPE & FIR BT IN PROPER CONDITION.  
COUNTY SURVEYOR ACCEPTED THE CS BT. 1969

Leonard Whitmore, 4-13-76

Index File No. \_\_\_\_\_ T. 4S R. 10W M. \_\_\_\_\_ Tract or Surv. No. 1/4 Cor. 13



**CORNER RECORD (SEARCH)** (Ref. FSM 7151.4)

Tract or Survey No. Cor. L-25

File No. 4S R. 10W R.D. Hebo County. TILLAMOOK

Merid. Will. N.F. SIUSLAW State ORE

---

**CORNER DIAGRAM**

**DESCRIBE CORNER MONUMENT FOUND**  
 GLO 1879 SET A CEDAR POST  
 20" SNAG, N. 56° W, 11 LKS.  
 48" SNAG, N. 6° E, 4 LKS.

---

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**  
 FOUND 1 1/2" GALV. PIPE 4" ABOVE GROUND ALONGSIDE A 4x4x10" POST.  
 FOUND A 30" FIR, N. 18° W, 15 FT. WITH A HELED FACE. I CHOPPED OPEN AND FOUND MARKS "CS 1/4" S 13."

---

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**  
 ABOUT 30 FT. TO THE S.W. IS THE ROTTED STUMP OF A SNAG. 2 1/2 FT. S. 46° W AS IN RECORDS I FOUND 2x4x36 REMNANT OF CEDAR POST THAT MAY HAVE BEEN THE ORIG. POST. ABOUT 25 FT. SOUTH IS AN OLD SIDE BLAZE ON WEST N. 56° W, 73 FT. IS A ROTTED STUMP.

---

**PHOTO IDENTIFICATION DATA**  
 Photo No. \_\_\_\_\_  
 Filed At \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

---

**PLANE COORDINATE POSITION DATA**  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

---

Signature: Leonard Whitmore Title: Forestry Tech Div: Timber Headquarters: Hebo Date: 5-7-69 7100-52 (3/68)

**REWITNESS**

I SET \_\_\_\_\_ "x" "x" "Post N.W. \_\_\_\_\_ feet  
 \_\_\_\_\_ "Hat Section S. E."

**COMMENTS:**  
 I REMOVED THE 3" U.S.F.S. 3" ALUMINUM CAP FROM THE 2 1/2" ALUMINUM PIPE, DROVE THE ALUM. PIPE FLUSH, AND SET A 5/8" X 30" I.R. WITH YELLOW COUNTY RANDOM CAP IN THE CENTER OF THE PIPE. SEE CS MAP # B-1079 FOR TRUE CORNER POSITION. 9-13-87 DM

**NOTE:** This erroneous corner position was preserved only for the purpose of preservation of position in the unlikely event that a metes & bounds tract had been initiated from the error position.

DATE: \_\_\_\_\_

PHOTO # 250715-1987  
 TILLAMOOK COMPLEX 6 MILLERS TITLE

\* County corner has affixed.

**NOTE**  
 L. WHITMORE IS A DEPUTY Co. SURV FOR POSITIVE OLD MONUMENTS FOUND. Re-witnessing CS. 8/69