

TILLAMOOK COUNTY REWITNESS #786
 SEC. 30 T 4S R 10 W., WM.
 MEANDOR COR. E.

HISTORICAL: GLO T4SR10W Page 43 1879 72" Spruce S82°E 58"¹⁴⁵
 40" Spruce N13°W 21"¹⁴⁵
 Book Hays "F" Page 49 Found GLO B.T.S. Year 1887
 Book 4 Pages 99 & 102 Found GLO B.T.S. Year 1961
 MAP B-566 Subdivision Section 30 4S 10 Year 1968
 MAP A-1028 South B.P.Y. Sec 30 4S 10 Year 1962
 Book 57 Page 70 Tied MC. to road traverse 1931


Refer To Ed Byerlee Field notes Sec 30 T4SR10W

CONDITION	FOUND:	Set fir Post 4 1/2 feet long - 3" diameter	GLO 1879
Found remains at dist	72" Spruce S82°E	58 ¹⁴⁵ = 38 ²⁸ feet	GLO 1879
Found Remains at dist	40" Spruce N13°W	21 ¹⁴⁵ = 13 ⁸⁶ feet	GLO 1879
Did Not Find	Set STONE 18" x 14" x 8" for corner		Hays Book "F" 1887
Found Scribing Visible *	14" Alder N80°30'E	22 1/2 feet	Book 4 page 99 1961
Found Standing ^{FACE VISIBLE} *	30" Spruce S27°30'E	40 1/2 feet	" 4 " 99 1961
Found Bottom Slope ok.	GLO CALL = ascend hill; bears NW-SE; AT 50 LINKS = 33° FEET		

COMMENTS: Found 5 foot x 3 1/2" Spruce post in mound of stone

REWITNESS

1 SET 2" Iron Pipe with Brass Cap and Two Tiles in Concrete
 W. feet



* 90" Hat Section WEST 072

NEW ACCESSORY:

COMMENTS: Had trouble stamping cap correctly and as a result the Brass cap appears chewed up

IN THE PRESENCE OF: _____

DATE: 5-72 PHOTO#: 2607 TITLE

* = County corner tag affixed.