

TILLAMOOK COUNTY REWITNESS #800

~~NEW~~ SEC. 33 4510 45 10
 1/4 COR. 4 5210 T 55 R 10 W., WM.

HISTORICAL: GLO Page 56 5510

September 1878	Survey by MELDRUM
Ran S89°39'E on N boundary of section 4 5210W -- variation 19°30'E	
Set a post 5' long & 4" dia for 1/4 corner @ 37.58 chains	
BT 12" Alder	S 5° E 35 LKS
BT 12" fir	N 18° E 106 LKS

See MAP A-118a by GJ PORSKY

CONDITION


FOUND:

	No evidence was found of GLO corner
With reference to MAP A-118a -- a survey by GJ PORSKY in 1912 -- the 1/4 corner between section 4 of 5210W and section 33 of 4510W was re-established, as shown on MAP B-579, by John L. Carlich (287 RS) County Surveyor.	

COMMENTS:

REWITNESS

SET 2" Iron Pipe with 3" Brass Cap over a native stake.
 Everything OK 4-8-81 I placed 10" form and concrete around Monument.
 96" Hat Section S. South 15 feet 2 ft



NEW ACCESSORY:

36" Hemlock	N 45° W	49.10 feet
9" Alder	S 65° W	21.28 feet
8-3-70		

COMMENTS: Located in a gully whose direction is east & west. Corner is located on south slope of gully. a small creek flows west through gully.

IN THE PRESENCE OF: George Urrey
 Gale Arthur

DATE: January 12, 1970

PHOTC#:

* = County corner tag affixed.

TITLE