

TILLAMOOK COUNTY REWITNESS #803

~~NEW~~ SEC. 33 T 4 S R 10 W., WM.
 Center $\frac{1}{4}$ COR. ~~SEE~~ ~~DEC~~ #

HISTORICAL:


Book 35	Page 62
MAP B-118	

CONDITION	FOUND:
POOR	Bottom of spruce limb was beside a rotted off fence post. Limb had been pointed by a Tool - an axe or knife - and driven in the ground. Top of the spruce limb was rotted away. NO BEARING TREES. WE'RE FILED IN THE COUNTY RECORDS. We found no legible evidence of bearing trees in the surrounding area. The position of the corner was established by Transit and chain.

COMMENTS:

REWITNESS

I SET $\frac{1}{4}$ CONCRETE & TILE
 2" Iron Pipe with 3" Brass Cap Marked as sketched at left of page.
 "x" "x" "x" N. ~~NE~~ North 20 feet
 * 84 " Hat Section ~~SEE~~



NEW ACCESSORY:

2" Iron Pipe with 3" Brass Cap		
Bearing Trees have yellow reference tags with "Do Not Cut Tags"		
BT-10" Spruce	S 60° E	6 20 feet
BT-14" Hemlock	S 73° W	41 38 feet

COMMENTS: 24" Creek is 25 feet west of Corner. The Sange creek is also 32 feet South of the Corner. Corner is in North - South fence line. SET AN 8" TILE AROUND 2" I.P. AND FILLED IT WITH CEMENT FEB. 72. ROGAR KNIPPEL GALE ARTHUR

IN THE PRESENCE OF:

Al Duncan
 Gale Arthur
 George Urvey

February 1972
 DATE: 4/30/69

PHOTO#:

* = County corner tag affixed.

TITLE 6104