

TILLAMOOK COUNTY REWITNESS # 804

Center West COR ¹⁶ SEC. 33 T 4S R 10 W., WM.

HISTORICAL: Book S-3 Page 62 Book 53 Page 466

G.J. Poyisky MAP A-118a
 MAP-B-579 by John Carllich (287 RS) County Surveyor

CONDITION


FOUND:

Rusty	1 1/2 Iron Pipe	± 3" Deep on projection of E-W and N-S fencelines.
	BT's were destroyed by construction of Highway 101	

COMMENTS: Found pipe fits MAP A-118a by G.J. Poyisky

REWITNESS

1 SET 2" I.P. with 3" Brass Cap -- CONCRETE & Tile MARKED AS SKETCHED



NEW ACCESSORY:

* 20" fir	N 65° E 111 ⁹¹	
* 48" Spruce	S 42° E 78 ²⁶	

COMMENTS: Corner is located ± 11 feet from west edge of Black Top of Highway 101 and ± .75 feet south of fence corner. The fence corner is to the Easterly side of NORTH. Corner is on west side of Highway 101. NO HAT SECTION WAS SET BECAUSE THE CORNER FALLS IN THE CHURCH YARD.

IN THE PRESENCE OF:

Al Duncan
 Gale Arthur
 George Urrey

DATE: 4-30-69

PHOTO#: REC

* County corner tag affixed.

TITLE
 G.W.U.