

REVISION 1976

USDA-FOREST SERVICE GPO: 940-117

Index File No. A-14 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. **#850** Cor. No.

T 55 R. 10W R.D. HEBO County TILLA

Merid. WILL N.F. SIUSLAW State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
 NOT ESTABLISHED ORIGINALLY BY GLO.
 PROPORTIONED BY GIERING UNDER FOREST SERVICE CONTRACT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 THE N.E. BT IS BLOWN DOWN.
 FOUND GIERINGS S.E. SPRUCE BT STILL STANDING
 FOUND BRASSCAP IN POSITION.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Estab. By _____ Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH

Signature: Leonard Whitmore Title: Forestry Tech Division: Timber Headquarters: Hebo Date: 6-1-72 7100-5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 BRASS CAPPED

W 1/6
S 3
TILLA
1971
C 13

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 SCRIBE 2 TREES;
 1" SPRUCE, N. 4° 12' E., 44 ¹⁰/₁₆ FT. "W 1/6 S 34 BT" BLOWN DOWN 1976
 1/4" SPRUCE, S. 31° 30' E., 65 ⁶⁶/₁₆ FT. W 1/6 S 3 BT Center
 NEW BT: 18" HEM., N. 76° E., 57 ¹/₂ FT. SCRIBED "W 1/6 S 34 BT" DIST. S 100' MAR. 21'

Leonard Whitmore, Tilla Co. Deputy Surveyor, 2-6-76

Work Done By: GIERING Title: ORLSP Date: 6-71 State Registration No. or Agency: COB

Certified Cor. Record Prepared? (Yes) No Filed At: TILLA CO COURT HOUSE Date: 6-77

REMARKS

Index File No. : T 55 R. 10W M. Tract or Surv. No. W 1/6 Cor. 3