

TILLAMOOK COUNTY REWITNESS

N. 7 010' SEC. 6
1/4 COR. 7 T. 55 R. 10 W., WM.
S. 6 GLO-T5SR10W Pg 53 & 13 - (1812)

HISTORICAL:	Book	Page	MAPS
	S3	196	A-684 WEA
Refer to Field notes by Stan			B-391 WEA
Skinner & Gale Arthur in Section			F-16-14 WEA
G T5SR10W on October 1965			A-1273 JLC
	BK 5	Pg. 271	


CONDITION GONE PIPE DESTROYED BY CATWORK

GONE	1 1/2" Iron Pipe	Set by Stan Skinner	See field notes
GONE	GLO SET 15x10x7 STONE	1812	GLO Pg 53 & 13
* FD NOW 40"	24" Spruce	S53°W 71.24	SA Skinner notes
* FD NOW 36.36"	24" Spruce	N64°30'W 58.33	SA Skinner notes

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE AND CEMENT FROM FOUND BK. 5. PG. 271 S. SKINNER B.T.S
* 86" Hat Section NORTH 1/2 FEET



NEW ACCESSORY:		

COMMENTS: THIS CORNER IS LOCATED ON A HILLSIDE ± 100 FEET WEST OF A GRAVEL ROAD. CORNER WAS DESTROYED BY CAT WORK.

IN THE PRESENCE OF: DAN McNUTT GALE ARTHUR

DATE: 12-17-76

PHOTO#: [Signature] TITLE

* = County corner tag affixed.