

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____

File No. D-17 T. 6S R. 10W D. HEBO County TILLA State ORE. #974

Merid. Will. J.F. SIUSLAW

CORNER DIAGRAM DESCRIBE CORNER MONUMENT FOUND

JIM ANLIKER, Longview-Fibre, 1953 SET PIPE & MKD
18" SPRUCE, S. 41° E., 15 5/8 FT.
2 1/2" HEM. S. 78° W., 22 1/2 FT. SCRIBED IN ROOT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND THE PIPE IN POSITION BUT BOTH WITNESS
TREES ARE BLOWN-DOWN.
EAST - S 7/8

PHOTO IDENTIFICATION DATA

Photo No. _____ Filled At. _____

Object Ident. _____ DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Ident. By _____ Signature _____

PLANE COORDINATE POSITION DATA

State OR Zone _____ Signature Leonard Whitmore Date 8-14-75

X _____ Y _____

Estab. By _____

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

FOUND A BENT 1 1/4" PIPE.
I SET IRON FENCE POST - ATTACH PENNANT TO DESTROY AND
SIGNS, Boundary

ACCESSORIES - DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDE

FOUND THE ORIGINAL N.W. STUMP, A 50" SAWED-OFF SPRUCE
N. 20° W., 12 FT. SCRIBE MARKS VISIBLE. Stump
I SCRIBE A NEW BT;
3 1/2" HEMLOCK S. 43 1/2° E., 31 1/2 FT. 1/4" STI OBT.
Leonard Whitmore, Tilla. Co. Deputy Surveyor 8-21-75

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

T. 6S R. 10W