

6 SR 10 W No. 3 E Cor. 1/4 Mer. WILL State ORE. N.F. SIUSLAW Dist. H. 680

Corner Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: POST 1890 # 984

5. Investigation Notes:
 Find 4.0 in. hemlock N. 74° E., 15 ft. with visible scribing BT. ^{visible}
 nail yellow bearing tree sign to said BT.
 Find 3.0 in. hemlock stump S. 37° W., 20 ft. with visible but not legible scribing.
 Find original corner post fallen upon the ground.

6. Signed L. Whitmore Title Forestry aid Date 1-2-1961

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Reestablish Survey
 Status E. S

PERPETUATION RECORD

Monument: put hemlock post in ground at exact spot of ^{old corner} ~~old corner~~

LEONARD & MERVIN (father) WERE / A. S. DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE ORIGINAL MONUMENTS

Accessories:
 new BT's
 34 in. hemlock S. 17° E., 32 ft., scribed by S 7 BT.
 34 in. hemlock N. 88° W., 30 ft., scribed by S 6 BT.

12. Set By _____ Title _____ Agency _____ Date _____ License _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____ (Date) (City) (County) (State)

14. Remarks: The new BT's are established by deputy surveyor M. Whitmore and witnessed by L. Whitmore and D. Jarmore. M. Whitmore
 This corner is approx. 200 ft. N. of a survey line blazed about 25 years ago.
 compass variation 19 1/2°