

USDA-FOREST SERVICE R.D. HeBo County TILLA
 Index File No. J-3 N.F. SIUSLAW State ORC.

T 6 S R. 10 DESCRIBE CORNER MONUMENT FOUND GLO 1890 SET POST + MKD;
 Merid. WILL. 10" ALDER, S. 31° E., 25 LKS.
 #987
7" HEMLOCK, N. 22° E., 45 LKS.

CORNER DIAGRAM

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND $\frac{1}{2}$ " STEEL TUBE FOR CORNER.
 FOUND 27" HEM., N. 14° E., 29 FT. WITH CHOPPED OPEN
 FACE, VISIBLE SCRIBE "S"
 FOUND 20" ALDER, S. 19° E., 16 $\frac{1}{2}$ FT. WITH BARK SCRIBES
 "1/4 S.B.T."

IDENTIFICATION DATA
 No. ETJ-5-108 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 At. HeBo SET $\frac{1}{2}$ " IRON ROD INSIDE TUBING.
 ct Ident. WITHIN 50' THE DISTANCES CORRESPOND WITH THE ORIGINAL BUT
 By. L. Williams DISCREPANCY OF BOTH BEARINGS MAY INDICATE THE S.E.
 Signature ALDER IS NOT ORIGINAL. THE BARK SCRIBES APPEAR TO
 BE 40 OR 50 YEARS OLD.
 E COORDINATE POSITION DATA THE TRUE CORNER POINT MAY BE DETERMINED BY USING
 THE ORIGINAL BEARING AND DISTANCE FROM THE N.E. HEMLOCK

Signature Leonard Williams Title State Tech Division HeBo Headquarters HeBo Date 5-1-73 7100-52 (3/60)

TITLE _____

DATE: _____

IN THE PRESENCE OF: _____

COMMENTS: No data for this side

NEW ACCESSORY: _____

County corner tag affixed.

PHOTO # REC. _____

CO. _____

DATE: _____

IN THE PRESENCE OF: _____

COMMENTS: _____

NEW ACCESSORY: _____

feet _____

" N.W. " Post _____

" Hat Section _____ S. E.

REWITNESS

I SET