T2N R9 & 10 W-- Corner to Sections 1-6-7-12. Rewitness:

Original Bearing Trees were: Hemlock 6" diam. \$70*W 95 links. Hemlock 7" " N68*W 83 "

For many years only the tree to the NW has been in existance— the SW tree has been gone. The NW tree had the blazes and iron marks up high. Two or Three years ago Ed Myers cut and logged this tree, removing all of the original Bearing Tree marks. However, the stump had been marked with an X mark. On Sept. 7, 1950, Harry McEwen, who has lived in Section with an X mown of this corner for many years, showed me this bearing tree stump. In his presence I measured from the stump 568×2 links, and set a $\frac{1}{2}$ inch pipe 3 feet long 2 feet in ground for the corner; and marked a new living bearing tree:

Two hemlocks growing togther from a common stump, stump about 5 feet diameter, bears N29*E, 94.3 feet distant, and blazed and scribed "S6 BT"

WA Markham Registered Engineer #1842

2. N. 9+10 W. - 1,6,7,12, REWITTHESS

Book I

184

11 / 18 CEU CEU (177)