

CHAINS

T 3 N, R 10 W $\frac{1}{4}$ Corner 35/36 Rewitness.

The GLO notes for the $\frac{1}{4}$ corner 35/36 call for:

Hemlock Post, and Bearing Trees--

Hemlock 8" N 90* W 4 Links
 " 7" N 22* E 8 "

In 1956 I found the Hemlock 8" to the West. The upper face plainly is a face, but the wood all rotted away; the lower face shows scribe marks plain "B T". The tree is down, twisted off at the roots, dead and rotten, but the roots still in place in the ground. From this Bearing tree I set a hemlock stake 2"x 2" scribed " $\frac{1}{4}$ S 35 & 36" and new Bearing Trees:

Hemlock 5" S30*E 9.7 feet, scribed on bark
 " $\frac{1}{4}$ S 36 BT 1842"

Hemlock 11" N 55* W 18.4 feet, scribed on bark
 " $\frac{1}{4}$ S 35 BT 1842"

In April 1963 I returned to this corner, found the old original BT and my new BT's and stake, all as described above; I set an iron pipe 1" x 5 feet in place of the stake, renewed the scribes in the bark of the two new bearing trees as listed above, and made an additional new bearing tree:

Hemlock 10" N 62* E 19.2 feet

Scribed in wood " $\frac{1}{4}$ S 36 BT 1842"

W A Markham
 Registered Engineer No. 1842.

