ŋ

	CHAINS	
A CONTRACTOR DESCRIPTION OF THE PERSON OF TH	,	Adjustment from temporary stake 2465.3 North 46.6 Et. to point on true line, and established the true line.
		Then begin at the 全 cor. bet. secs. 9 & 16.
		NO 39' E on a true line through the center of Sec. 9.
	1328,5	Set temporary stake.
	2648.4	Intersected the true line S 89° 24' W through the center of Sec. 9 at a point 2671.7 ft., S 89° 24' W, of the \$\frac{1}{4}\$ cor. to secs. 9 & 10.
		The center of sec. 9 at the point of intersection of true lines.
		Set a la inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: Ca S9 1950 199.
		from which:
		An alder, 4 inches in diam., bears N 68° 30° W, a distance of 9.3 ft., scribed: C \(\frac{1}{4}\) S9 199.
		An alder, 3 inches in diam., bears S 37° E, a distance of 12.8 ft., scribed: C & S9 BT.
		Placed a metal location poster on a 66 inch fir snag & marked it: Sec. 9 TlN R7W C 4 27.8 ft. N 11 E.
		Placed a mound of stone around corner.
	Andrew College Control of the Contro	s o° 39' W.
	1324.2	Point for center south 1/16 corner. Adjustment from temporary stake 1328.5 S 0 39° W. a distance of 4.3 ft.
		At the point for CS 1/16 cor.
		Set a la inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: S 1/16 C - C S9 1950 199.
	The state of the s	Nailed a metal location poster in a fir stub, 24 inches in diam., & marked it: Sec 9 TlN R7W CS 1/16 Cor. 31.3 ft. S 55° W.
		Placed a mound of stone around corner.
		From the 4 cor. bet. secs. 9 & 10.
		S 89° 24' W.
		Point for center West 1/16 cor.
	4016.7	Adjustment from temporary stake 4106.5 North 76.7 feet, East 89.8 feet.
	Balancer III repair J	At the point for CW 1/16 cor.
		Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: W 1/16 C C S9 1950 199.
	1	

BOOK 2