CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 5, 6, 31, and 32, T. 1 & 2 S., R. 7 W. W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a;

30" Hemlock bears N31°30'W 39 lks; now missing.
12" Hemlock bears N30°30'E 89 lks; now 18" stub 2½' high; scribe marks BT exposed.

12" Hemlock bears S35W 110 1ks; now 12" stub 3' high; exposed cast of scribe marks W S6.

16" Hemlock bears S67°45°E 70 lks; now 20" stub 3' high; exposed scribe marks BT.

RESTORED CORNER AND BEARING TREES

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S31 S32 S6 S5 T2S 1952 2311", $2\frac{1}{2}$ ° in ground, from which a:

5° Fir stump bears S62°30°E 39.6°; scribed S5 BT.

4" Alder bears N45E 22.5"; scribed S32 BT.

56* Fir stump bears S64W 68.2°; scribed T2S R7W S6 BT 2311.
56* Fir stub (leaning East) bears N30W 25.9°; scribed S31
BT.

Placed an Oregon State Board of Forestry metal location poster on 56" Fir stump BT and marked it: Sec 6 T2S R7W Sec Cor 68.2" N64E.

Dated February 27, 1952.

This corner was restored by

Don D. Davis Asst.Forest Engineer

under my direction.

Present and witnessed by

Compassma

BOOK 2