CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 7 and 12, T3S, R9 and 10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

 $2\frac{1}{2}$ Elder bears S52W 100 lks.; now missing. 3" Elder bears S16E 110 lks.; now missing.

RESTORATION by County Surveyor December 7, 1903

Post (now missing) from which a:

20" Hemlock bears N27E 48 lks.; now missing, point falls in cat road. 10" Spruce bears S67W 16 lks.; now 23" stump, portion of scribe mark visible on rotted face.

RESTORATION by W. A. Markham (no date indicated)

14 x 3 iron bolt (found out of place, N72W 1.7) from which a:

14" Hemlock bears S20E 19.0 feet; now 16" stub 4" high, scribe marks 4 S 7 T in bark laying on the ground.

RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S12 S7 1960 RS401", 33 inches in ground, and from which a:

17" Fir bears N30W 53.6 ft.; scribed 1/4 S12 BT.
17" Hemlock bears S302E 129.5 ft.; scribed 1/4 S7 BT RS401.

Oregon State Board of Forestry metal location poster on 17" Hemlock BT. Set 4" x 4" x 50" white painted Cedar post 1.5 S.E. of pipe.

Dated March 14, 1961

Restored by

Present and witnessed by H. Russell

R. Cop G. E. Nylund MAY 10, 1837 Richard A. Morris

REGISTERED
OREGON
LAND SURVEYOR

487