CHAINS

page # 3

Post (Missing)
24" Fir N40°W 6 links (not found)
16" Fir S32°W 17 links (not found)
RE-Established:
Set 5/8" x 30" iron pin 26" in ground
Set 4" x 4" x 48" white post 1 foot East of pin
10" Fir S3°45'W 18.6 feet, scribed "1/4 S13BTRS691"
12" Fir N10°30'W 4.9 feet, scribed "1/4 S12BT"
Yellow corner tag on 12" Fir BT
a partly rotted, broken top 14" Hemlock stump
scribed "BM823.9" bears N51 15'E, 58.1 feet.

NORTH EAST 1/16

ESTABLISHED:

Set 5/8" x 30" iron pin 26" in ground Set 4" x 4" x 48" white post 1 foot South of pin 6" Fir S65°30'W 21.6 feet, scribed "1/16 S12 BT RS691" 4" Fir S36°45'E 49.3 feet, sdribed "1/16 S12 BT" Yellow corner tag on 6" Fir BT Old Stone fireplace bears N75°15'E 96.5 feet

CENTER EAST 1/16

ESTABLISHED:

Set 5/8" x 30" iron pin 27" in ground

Set 4" x 4" x 48" white post 1 foot South of pin

21" Fir N73°15'E 30.0 feet, scribed "1/16 S12BT"

26" Fir S35°30'E 39.3 feet, scribed "1/16 S12BTRS691"

Yellow corner tag on 21" Fir BT

A stone monument dedicated to "The Pioneers of Leno Hill"

bears N3°45'W 61.6 feet

This corner is located 31 feet East of the center of Highway 18 at the South end of a turnout.

REGISTERED
OREGON
LAND SURVEYOR

JULY 9, 1965 John E. Hollingsworth

ohn E. Hollingsworth

BOOK 3