

CHAINS

5S R10W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

Section Corner common to Sections 22-23-26-27, W.M.,  
Tillamook County, Oregon

ORIGINAL: Found

3" x 3" hard limb 2" above the ground-18" in ground.

Am convinced is the lower part of the original post.  
36" fallen Hemlock, S.50°W., 13 ft. (as in orig. notes)  
with a rotted-out witness face on the under-side  
of the log.

The original S.E., N.W., and N.E. Alder BTs. are  
entirely gone.

Corner is 13 ft. south of the west fork of Austin Creek.

RESTORED: I set  $\frac{1}{2}$ " pipe 30" above ground with a rock mound.

Marked new BTs. as follows:

43" Hem., N.24°E., 81 ft. mkd. T5SR10WS23CSBT

40" Spruce, N.32°W., 78 ft. mkd. T5SR10WS22CSBT.

28" Hem., S.65°E., 19 ft. mkd. T5SR10WS26CSBT.

56" Hem., S.16°W., 51 Ft. slope dist. mkd. T5SR10WS27CSBT.

RESTORED BY:

Leonard Whitmore, Tillamook County Deputy Surveyor

Dated: 2-2-67

WITNESSED BY: Hobart Means

(See Reverse side for further information on Corner)

CHAINS

2-2-67  
 COR. TO SECS. 22-23-26-27  
 ON FILE AT THE HEBO R.S. IS RECORDED EARLIER INFO ON THIS CORNER BY CURTIS NESHAEIM HEBO R.S. ADM. GUARD 1-3-40.  
 AT THAT TIME HE SAW THE ORIG. S.W. BT DEAD AND DOWN LYING ACROSS THE WEST FORK OF AUSTIN CR. (36. HEMLOCK S. 50° W. 10 LKS. WITH VISIBLE MARKS TSSR 10W S 27 BT ON UNDER-SIDE OF THE LOG) HE MENTIONED PUTTING A BLAZE ON THE TOP SIDE OF THE LOG. HE MADE NO REFERENCE OF THE NE NW OR SE ALDER BT'S OF WHICH WERE APPARENTLY MISSING AS OF NOW.  
 I FOUND THE ROTTED OUT WITNESS FACE UNDER NEATH THE LOG WITH ALL MARKS GONE. NESHAEIM'S BLAZE IS ON THE TOP SIDE OF THE LOG WITH A OLD RUSTED LOCATION TIN (PAINT AND MARKS GRODED AWAY) NAILED ON THE BLAZE.  
 MEASURING OUT APPROX. 10 LKS. N. 50° E. FROM THE STUMP HOLE OF THE UP ROOTED BT I FOUND AT THIS POINT A 3"x3" TOP

OF A HARD LIMB OF EITHER FIR OR SPRUCE EXTENDING 2 INCHES ABOVE GROUND. I CAREFULLY PULL THE LIMB FROM THE GROUND AND FIND IT 18" LONG. UPON CAREFUL EXAMINATION I AM CONVINCED THIS WAS THE LOWER PART OF THE ORIGINAL POST, THE TOP PART ABOVE THE GROUND HAS ROTTED AWAY. THE DISTANCES AND BEARINGS TO THE STUMP HOLE AND THE SPOCK NEARBY CORRESPOND WITH THE ORIG. FIELD NOTES.  
 NO LARGE TREES HAVE GROWN OR FALLEN IN THIS IMMEDIATE AREA, THEREFORE BEING CONVINCED THIS POST WAS SET BY MAN I USE THIS POINT IN RESTORING THIS CORNER.

Leonard Whitmore  
 Tillamook Co. Sup. Surveyor  
 Mahant meadows, witness  
 2-2-67