County Surveyor's Record, Tillamook County, Oregon

At the quarter corner common to Secs. 6 and 7., T. 3 S., R. 6 W., W.M., Tillamook County, Oregon, I find the pipe set by Geo. Rigby, Cadastral Engineer, missing and the bearing trees described by him as follows:

40" Hemlock N 42 $^{\circ}$ E 22 links Now a stump B.L.M., Bearing Tree Tag. 60" Fir S 16 $^{\circ}$ W 52 links Now a stump.

Set a 1" X 36" iron pipe for the corner in a mound of stones.



July 23, 1969

Graydon M. Adcock

Arther E. Mosher

WILLAMETTE INDUSTRIES, INC. Dallas, Oregon