## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally set in 1872, 40 chains West of  $\frac{36|31}{6}$  . A post was set from which a:

30" Hemlock N 35° E 35 lks.

10" Hemlock S 32° E 25 1ks.

DIAGRAM A

1/4 Corner

36 (Only)

Reference:

Plat dated July 1973 by Timberland Services, Inc. under my stamp.

## Description of corner evidence found:

I found a 1/2" iron pipe, and the SE BT. The BT has been up-rooted. Scribed marks are visible but illegible. I found three recently marked BT's.

6" Hemlock S 87° W 3.1 ft.

10"mkd "LS 784"

10" Hemlock N 34° W 25.9 ft.

mkd "T 5 S R 11 W 1/4 S 36 BT"

10" Hemlock N 24° E 33.8 ft.

mkd "T 5 S R 11 W 1/4 S 36 BT"

All above mentioned BT's appear to have been marked by LS No. 784.

Description of manument and accessories I established to perpetuate the original location of this corner

I set a 2 1/2" X 30" Galvanized iron pipe with a flared bottom and brasscap riveted to the top marked:

T 5 S R 11 W

1/4 S 36

1973

RLS 942

The above mentioned BT's are standing and vigorous. I marked no additional trees.

Witnessed: M. Jackson

Office of Surveyor Country of Trus MOOK

Stare of OREGON ... I hereby certify that the within instrument was filed in this office forecord on the 20-day of AUGUST ... 1973 . at 20'clock A m., (signed)

I COUNTY OFFICIAL) by (DEPUTY)

Set this 7th day of June 1973

) O n

BOOK 5 Edgar R Cook

Graduate Forest Engineer

Form R6-7100-57 (9/66)

TIMBERLAND SERVICES, INC. P.O. Box 668 - Albany, Ore. 97321 Phone: 928-3520 REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DULY 17. 1970
KENNETH M. WIGHTMAN II
942