## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner has never been established.

DIAGRAM F

1/4 Corner

S 6 Only

Reference:

Plat dated July 1973 by Timberland Services, Inc. under my stamp.

Description of corner evidence found:

None

Description of manument and accessories I established to perpetuate the original location of this corner

I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T 6 S R 10 W

1/4 S 6

1973 RLS 942

At proportionate measurement based on platted distances & acreages. From which:

10" Hemlock S 36° E 50.6 ft mkd " 1/4 S 6 BT" 14" Alder S 30° W 15.0 ft. mkd "1/4 S 6 BT"

Slope: 65% Aspect: North

Witnessed: E. R. Cook

Set this 19th day of July 1973.

BOOK 5

234

TIMBERLAND SERVICES, INC.
P.O. Box 668 - Albany, Ore. 97321
Phone: 928-3539

OREGON JULY 17. 1970
KENNETH M. WIGHTMAN II
942

REGISTERED PROFESSIONAL

AND SURVEYOR

Form R6-7100-57 (9/66)