CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM Standard Corner

31 | 32

6

Reference:

This plat dated July 1973 by Timberland Services, Inc. under my stamp.

Description of corner evidence found:

Found G.L.O. Brasscap at corner with 3/4" aluminum pipe 0.5 NW 1' above ground.

U.S. Dept of the Interior Unlawful to Disturb

T 5 8 R 10 W S 31 S 32 S 6 1962

Cadastral Survey Bureau of Land Management From which:

8" Alder N 84° E 18 1ks "X" & "BT" visible I mkd: "T55SS R 10 W SC S 32 BT"

8" Spruce N 27° W 18 1ks Scribe scar visible

36" Rotted Spruce stump N 20° W 6 lks. "W BT" visible (original BT)

Description of manument and accessories I established to perpetuate the original location of this corner

I retagged these trees & set 6' steel posts with boundary signs 3' NE & 3' E.

Witnessed: E Tatro

B Jones

OHILLOI COUNTY SURVEYOR COUNTY OF THE MANOOR . I hereby certify that the within instrument was filed in this office day of AUGUST , 1973 , at 920'clock m., (signed) COUNTY OFFICIALI (DEPUTY) REGISTERED

Set this 30th day of May 1973,

BOOK 5 '

235

TIMBERLAND SERVICES, INC. P.O. Box 668 - Albany, Ore. 97321 Phone: 928-3539

OREGON KENNETH M. WIGHTMAN II 942

PROFESSIONAL

LAND SURVEYOR

Form R6-7100-57 (9/66)