## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

This corner was originally set by the G.L.O. in 1880 under Contract No. 364. They set a stone 10"x6"x4" for the corner and built a stone mound.

DIAGRAM	tiete kirist heiden heide daal kein deur zu zu zu zu zu ze deur zu ze deur zu ze deur zu ze deur zu ze ze zu d
T 5 S	R 9 W
1	/4
S 6	S 5

## Description of corner evidence found:

I could find no evidence of the original corner.

## Description of monument and accessories I established to perpetuate the original location of this corner

At proportionate distance, I set a 2 1/2" x 30" galvanized iron pipe with a brasscap riveted to the top marked:

From which:

18" Fir S 26° W 25.5 feet mkd. "1/4 S 6 BT" ll" Alder N 72° E 25.3 mkd. "1/4 S 5 BT" 25.3 feet

All bearing trees have been banded with red paint and attention signs and BT tags have been attached. All scribes have a 3/4" brass washer, with "LS 942 engraved on it, nailed in the face.

Witnessed: E. W. Tatro

Office of	County of	
State of, I hereby certify the for record on the	********	PROFESSIONAL LAND SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	L TAND BURVEYOR
Set this 11th day of February 1975	5	12 Amil NA
Morte a. Cook	321	Emit M. Wightmen
Monte A. Cook	o hi l	JULY 17 1070
Forest Technician		KENNETH M. WIGHTMAN II

Form R6-7100-57 (9/71)



TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Box 668 Albany, Oregon 97321 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

☆ GPO 796-333

BOOK 5 1