CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally set by the G.L.O. in 1880 under contract No. 364. They set a post from which:

> 5" Willow S 22° W 30 lks. 40" Fir N 60° W 122 lks.

DIAGRAM T 5 S R 9 W S 5 1/4 S 8

Description of corner evidence found:

I found no evidence of the original corner or its accessories.

Description of monument and accessories I established to perpetuate the original location of this corner

At proportionate measurement, I set a 2 1/2" x 30" galvanized iron pipe with a brasscap riveted to the top marked:

> T 5 S R 9 W

> > 1/4 S 5 S 8

1975

from which:

24" Fir S 14° E 14.0 feet mkd. "1/4 S 8 BT"

21" Fir N 16° W 19.1 feet mkd. "1/4 S 5 BT"

All bearing trees have been banded with red paint and attention signs and BT tags have been attached. All scribes have a 3/4" brass washer, with "LS 942" engraved on it, nailed in the face.

Witnessed: D. M. Jackson

..... County of

for record on the day of

by (CEPUTY)

Set this 6th day of February 1975

Edgar W. Lamb Engineers Aide

Form R6-7100-57 (9/71)

324

TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Box 668 Albany, Oregon 97321 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

PROFESSIONAL LAND SURVEYOR

REGISTERED

☆ GPO 796-333