History of original corner establishment:

1887 GLO Survey set post 36" Fir bears N 68° 30' W 72 1ks 20" Fir bears S 45° 45' W 19 1ks 24" Fir bears S 45° E 35 1ks DIAGRAM

T6S R9W

SE Cor Sec 1

NE Cor Sec 12

Closing Corner

Description of corner evidence found:

Found 3/4" galv. pipe and 4" x 4" white post 1 ft. East Found original 24" rotted fir stump S  $45^{\circ}$  45' W 12.5 ft. Scribe marks "9W 12" showing The original NW Bearing Tree is a rotted stump The original SE Bearing Tree is missing 7" Fir bears N  $44^{\circ}$  W 32.5 ft. to side center with blazes healed over and Bearing Tree sign

Corner is located approximately 34 ft. North of logging road

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2" galvanized pipe with 3" Brass Cap, 6" above ground stamped:

Placed galvanized pipe in hole on North side of monument Placed steel post with Attention sign 3 ft. W of monument 6" Fir bears N 89° W 23 ft. to side center scribed "CC T6S R9W S 12" on upper blaze and "BT" with brass washer on lower blaze. Placed Bearing Tree sign facing monument and Attention sign on back of Bearing Tree. Painted 6" red band and face of blazes on all bearing trees. Placed Attention signs on all witnesses.

T6S
R9W
CCS 1 R8W
S 12 S 7
1975
PE 1956

Lee map B.701

Form R6-7100-57 (9/71)

☆ GPO----798-276