DIAGRAM

RIOW

T45

512 R9W

S13 | S18

History of original corner establishment:

Corner established by Henry Meldrum, Deputy Surveyor, under Contract No. 301, dated Sept. 13, 1878. Original survey states:

Set fir post, 5 ft. long, 4 ins. sq., for cor. to Secs. 12, 13, 7 and 18; from which:

A fir, 20 ins. diam., bears N.33°W., 95 lks. dist.

A fir, 28 ins. diam., bears N.43°E., 250 lks. dist. A fir, 30 ins. diam., bears S.41°W., 395 lks. dist.

A fir, 14 ins. diam., bears S.50°E., 196 lks. dist.

Corner is common to Sec. 12 and 13 only because of a closing corner T4S, R9W., to Sec. 7 and 18 set by Charles E. Branson, Deputy Surveyor, Contract No. 687, June 8, 1898.

M. Whitmore Deputy Surveyor, Tillamook Co., perpetuated and recorded this corner on April 17, 1953.

Description of corner evidence found:

Wood post 2"x3"x20" 1-1/2 ft. above ground. Marked S13 on south side. Set by M. Whitmore April 17, 1953. 3/4" galvanized pipe 2.0 ft. above ground next to post.

50" fir snag, N43°E, 164.9 ft. dist. scribed: T4S, R9W, S7 BT (original BT snag is 25 ft. tall).

Multi-stemmed alder 40" diam., N50°W, 43.2 ft., bark scribed: T4S, R10W, S12 BT Set by M. Whitmore April 17, 1953.

Multi-stemmed alder 18" diam., S46°W, 42.0 ft., bark scribed: T4S, R10W, S13 BT. Set by M. Whitmore April 17, 1953.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30" x 2-1/2" iron pipe with a 2-1/2" diam. brass cap, flared on bottom, mkd:



Buried 3/4" diam. pipe alongside of cap. Painted 6" bands around B.T.'s with red paint. Attached attention signs on back side of B.T.'s Set a 6 ft. fence post with attention sign. Attached 3 ft. 'W' of cap. Posted BT tags.

Witnessed: F. Wratni

REGISTERED PROFESSIONAL AND SURVEYOR "Yearan Anda OREGON L. W. HUNNEMULLER 1050

Office of COUNTY SUBJETURE	County of Trumphous
State of	
for record on the	, 19¥
al Calin os	by
(COUNTY OFFICIAL)	(DEPUTY)
for record on the Aday of	y that the within instrument was filed in this office, 19. by

Form R6-7100-57 (9/71)

☆ GPO---798-276