## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

**DIAGRAM** 

T 4 S R 8 W C N N SW 7/256 S2 WC

L

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

> At proportionate distance, corner point falls in creek. I, therefore, set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and brasscap rivited to the top marked:

T4S R8W

S2 C N N SW 1/256 WC 1977 RLS 1073

From which;

18" Alder S64W 94.5 feet Mkd. "X B.T." Power pole #BE-D-1 R 18-SP S72W 83.0 ft SW corner of cabin N38W 119.0 ft SE corner of cabin N13W 140.5 ft

Witness corner is NO2° 35' 55" W 30.00 feet from true corner.

I set a steel fence post with signs and properly marked bearing trees. See my B. 764

Witness; J. McDonald

Engineering Technician

Office of SUNTY DURINE YOR County of TILLAMON State of Office of the William II State of Office (ENNETH M. WIGHTMAN II 942


COUNTY SUBJECTOR

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

Book 6 Pg 29



TIMBERLAND SERVICES, INC. 1010 Airport Rosd P. D. Box 668 Airport Progre 37321 Oregon 37321 Fairphone 18031 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

REGISTERED OFFESIONAL EGON

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

EDGAR R. COOK 1073