CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM T 4 S R 8 W

> C-S-NE-SE 1/256

> > S2

Q

Description of corner evidence found:

None

SEE RESET OF THIS

SEE RESER
FOR ORNER 13181 Duncan
C.S.

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T4S R8W

From Which,

S2

C-S-NE-SE

1/256

1977 RLS 1073 20" Alder S 74° E, 3.4 feet

Mkd "C-S-NE-SE 1/256 S 2" "B.T." Bark Scribed

38" D. Fir N 08° E, 22.7 feet

mkd "C-S-NE-SE 1/256 S 2" "B.T."

Set 6' steel fence post with property boundary and land survey monument signs. All bearing trees have brass washers, attention signs, bearing tree tags and red painted bands.

Witness: Ed Tatro

See / Map B- 76 4

Engineering Technician

Office of OUNTY DURNEHAR County of NAMANICAK State of ... DECOU........ I hereby certify that the within instrument was filed in this office KENNETH M. WIGHTMAN II

for record on the 8th day of ANGWAT 19.7. LICALL ON COUNTY DURVEYOR

REGISTERED PROFESSIONAL LAND SURVEYOR

Form R6-7100-57 (9/71)

Book 6

(COUNTY OFFICIAL)



TIMBERLAND SERVICES, INC. MIO Airport Road P O Box Albany, Oregon 97271 Telegiberes (SCC 975 P464)

AT - SURVEYBY: - ENGINEERING EARC USE PLANNING - ROADS FORESTRY CONSULTING

PROPESSION OREGON EDGAR R. COOK

1073

REGISTERED