County Surveyor's Record, Tillamook County, Oregon

	CHAINS		
	CHILING		
		(172)	
		CE 16 Sec 32 4518	At the first designation of the first designat
	a de la companya de La companya de la co		VIII.
		Found old 1901 \$ 1896 Bearing	
		Tree which Are one in Same	
		1901 Bearing Tree 60" spr 5408	
		132 Now 6/" Burned stong	
		1896 40" Spx N32 E 5 EH	1
		This Tree Has seribing on]
		Both Bearing	
		1901 16 C5 M"	
		1896 6 87"	
		The outhor Bearing Tree was the	
		Same For 1901-1896 it 15	
		Now gone it was:	
		1896 South 1,98	
. *		1901 500+4 9.24	
		Iset A 3" Iron Pipe For The	
		Cor From 1901 Bearing Thee	
		Also A 4"x 4" x 48" White Ced Post	The state of the s
		OS SWY of COV	
100			
		The 1896 Cor Position is South 8th From Mol Cor	
		South 8= From 1401 COL	
		New Bearing Trees Are	}
		24 10"Hem N 49° 41' N 8721 @ 11°30	
.		24 10"Hem N49°41' N 872 @ 11°30 12 81Hem S42°36 N 11328 CE; S28 BTCS	
		A. Duncon GArthur SSKinner 5-1-67	
			·
	}		E