RESTORED CORNER FOR STATE OF OREGON -- DEPARTMENT OF FORESTRY

One quarter corner common to Sections 19 and 30, T3N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

15" x 14" x 6" Basalt stone (destroyed by road construction) from which a:

6" hemlock bears S16°E 18 lks.; missing. 14" hemlock bears N22°W 35 lks.; missing. 2 lk. brook bears East 330', runs Northeast; in place.

On July II, 1951, I ran a compass line from Section corner 19, 24, 25, and 30, T3N, R7&8W East, var. 22°E and found remains of original bearing tree N22°W 35 lks. from 1/4 corner point. Then I ran East from the 1/4 corner and failed to find the section corner 19, 20, 29 and 30. A few weeks after I had done this, Erikson Logging Company built a road through the 1/4 corner bearing tree, destroying it. On October 24, 1985 I retraced my old compass line notes which are on file with the State Forestry Department. By tying $t \dot{q}$ the topography calls I noted I was able to pinpoint the location of the 1/4 corner which I showed Loren Steele. He later set a pipe at this location.

RESTORED

At the point Richard Morris showed me I set 2" x 36" aluminum pipe with 3 3/4" aluminum cap marked "STATE OF OREGON DEPARTMENT OF FORESTRY T3NR7w 1/4 ST9S30 1985 RS401" 3T inches in ground, and from which a:

15" alder bears N16 3/4°E 22.8 ft. to face; bark scribed 1/4 S19BT. 13" alder bears S26 1/2°W 34.4 ft. to face; bark scribed 1/4 S30BT. Road bears West 43.9; crs. S32°W by N37°E.

Set 4" x 4" x 60" white painted Cedar post S.E. 1.0 ft. from corner pipe. Oregon State Forestry Department metal location poster on 15" Alder BT.

Dated October 30, 1985			
Restored by Loun A. Stale	under	my	direction.
Loren Steele			

Present and witnessed by S. Ellis 0. Hendrick

OREGON MAY 10, 1957 RICHARD A. MORRI

REGISTERED PROFESSIONAL

SURVEYOR

Book 4 276