TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to Sections 31 & 32 T.1S., R.10W.W.M. and

Sections 6 & 5 T.2S., R.10W., W.M.

R10W T1S S31;S32 --+--S6;S5 T2S 1969 RS 287

I found a 3" Tillamook County Brass Cap in an 8" concrete cylinder as described on Tillamook County Rewitness Cards #330 & #448 in good condition.

History of found Monument

I found this monument to be as reported on the above said rewitnesses and the accessories found and/or set at that time to now be as follows:

30" fir S.77*W. 171ks; (Now a rotten stub 5' high).

8" pine N.78*W. 12.0'; (Now an uproot).

8" pine N.53*E. 8.1'; (Now 9" broken off pine snag).

16" pine S.51*W. 17.4'; (Now 19" distance to face is 17.3').*

14" pine S.30 E. 18.6'; (Now 15", leaning, distance to face is

18.4'.).*

18" spruce N.47*E. 14.9'; (Now 21").*

86" hat section post South 12.8'; (Now gone).

New accessories

84* hat section post South 1.5'.*

Monument Location

This corner is located approximately 175' South of Pearl Street in Netarts, and Approximately 30.4' easterly of an unimproved street, (Pine Street), on a stabilized dune.

In the presence of Dan McNutt & Al Dvorak

June 1989

Title allan & Duncan, C.S.

