TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to Sections 31 & 32 T.2N., R.6W., W.M. and

Sections 6 & 5 T.1N., R.6W., W.M.

T2NR6W S31;S32 --+--S6;S5 T1NR6W 1987

I set an 8" Oregon State Highway cast iron monument case around the found 1 1/2" iron pipe with 3" Tillamook County Surveyors Brass cap set in 1987, (see Tillamook County Surveyors rewitness cards #3 a & b).

History of found Monument

I found this monument to be as reported on the above said rewitness and the accessories found and/or set at that time to now be as follows:

23" cedar N.87*E. 192.67'; (now 27" scribing visible in partially healed face).*

10" cedar S.57*E. 175.89'; (now 12" scribing visible in partially healed face).*

26" fir S.79*W. 247.55'; (now 29" face overgrown).*

24" fir N.72*W. 236.05'; (now 26" scribing visible in partially healed face).*

*indicates yellow metal Tillamook County location tag attached.

Monument Location

This corner is located in the pavement on the North shoulder of Oregon State Highway #6 (Wilson River Highway), where there are large cuts on the South and North sides of the road.

Title_____

In the presence of Dan McNutt & Al Dvorak

June 1989

PROFESSIONAL LAND SURVEYOR

LIME Duncan, C.S.

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
7 9 3

REGISTERED

SEP 18 1989