TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to Sections 32 & 33 T.2N.,R.10W.,W.M. and Sections 4 & 5 T.1N.,R.10W.,W.M.

T2NR10W 532|533 ---+--55|54 T1NR10W 1990

I set a 1 1/2" iron pipe with 3" Tillamook County Surveyors Brass Cap in a 10" concrete cylinder at the found position of a truck axle, (1 3/4" X 42"), as reported on Tillamook County Surveyors Map #F-40-139.

History of found Monument

I found this monument to be as reported in the above said map. And the bearing trees found and/or set at that time to now be as follows:

5' cedar stump 5.75*W. 15.8'; (found, now large cedar stump with yellow tag at position). [Original 48" cedar 5.75*W. 24 links].

2' hemlock stump N.45*W. 17.2'; (found, now rotten stub approximately 4' high axe marks visible). [Original 16" hemlock N.40*W. 26 links].

12" hemlock stump N.30*E. 17.8'; (found, now rotten stub approximately 5' high. Scribe marks visible on solid face. Now bears N.43*E. 17.8'. [Original 6" hemlock N.45*E. 48 links], distance appears to have been transposed between the SE and NE bearing trees.

*2' cedar 5.50*E. 80.0'; (found, now 36" cedar with top broken out scribing visible on partially healed face).

In addition I found a rotten 24 "hemlock stump 5.30*E. 32.25' [Original 11" hemlock 5.30*E. 27 Links], distance appears to have been transposed between the SE and NE bearing trees.

Maps of reference

F-40-139 P.L.Thompson PE

1953

B-437 R.M.Morris R5 401

1961

REGISTERED
PROFESSIONAL
LAND SURVEYOR

allan & Duncy, C.S.

APRIL 23,1990

ALLAN E DUNCAN

APR 23 1800

Page 1 of 2

TILLAMOOK COUNTY SURVEYORS OFFICE Section Corner common to Sections 32 & 33 T.2N., R.10W., W.M. and Sections 4 & 5 T.1N.,R.10W.,W.M.

New Accessory

*13" cedar 5.8*W. 8.28'; scribed T1NR10W55B.TCS.

*15" cedar N.86*E. 1.34'; scribed T2NR10W533B.T. *13" cedar N.34*W. 21.69'; scribed T2NR10W532B.TCS.

*84" hat section post North 1.5'.

All distances to new bearing trees measured to nail with brass washer in face between scribe marks "B" & "T".

*indicates yellow metal Tillamook County location tag attached.

Monument Location

This corner is located 400' Easterly of a Y intersection in a logging road and approximately midway between the two roads formed by the Y. I laid found axle alongside monument. I also attached a Tillamook county location poster on a 15" hemlock on the South side of a gravel logging road approximately 260' North of the corner.

In the presence of Dan McNutt & Al Dvorak

March 1990

Title

REGISTERED PROFESSIONAL LAND SUDVEYOR

page 2 of 2

allon & Duncar, C.S. OREGON JULY 14, 1967 ALLAN E. DUNCAN APRIL 23, 1990

