TILLAMOOK COUNTY SURVEYORS OFFICE

Section corner common to sections 9,10,15,&16 T.25.,R.9W.,W.M.

T2SR9W S9 | S10 ---+--S16 | S15 RS 287 1974

I found a 2" iron pipe with a 3" Tillamook County Surveyors brass cap, I set in a 10" cast iron monument case in concrete. (See Tillamook County Surveyors rewitness card #380).

History of found Monument

I found this monument to be as reported on the above said rewitness, and the accessories found and/or set at that time to now be as follows:

Power pole #E4-200-15 N.49*30'E. 24.95'; (Found, okay, new pole #101100). Set finish nail with brass washer in scribed triangle at distance.

Power pole S.0*30'E. 18.97'; (Found, new pole #151801, now 18.87' to nail with brass washer in scribed triangle).

NW corner of house 5.38*E. 83.2'; (found, 83.3' to foundation).

NE corner of house S.47*W. 117.9'; (found, 117.7' to foundation).

*84" hat section post South 17.85'; (found, now S.9*W. 17.8').

* Indicates yellow Tillamook County corner tag affixed.

Surveys and rewitnesses of reference not listed on card #380:

B-880 1979 Archie B. Chapman L.S.27 B-882 1980 John L. Carlich R.S.287 A-5751 1989 C. W. Cook L.S.1098 A.M.A. 12 page 80 1920 Andrew M. Austin R.E.1118

Monument Location

This corner is located in the paved apron between Brickyard road and Burbank road.

In the presence of Dan McNutt & Al Dvorak

July 1990

Title

JUL 24 1990

OLALAYORS OFFICE

REGISTERED PROFESSIONAL LAND SURVEYOR

Ban G. Duncan, C.S.

OREGON JULY 14, 1967 ALLAN E. DUNCAN 7 9 3