OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT **Tillamook County Surveyor's Office**

| COUNTY: Tillamook CORNER DESIGNATION: One-quarter corner common to and 5, Township 2 South, Range 9 West, W.M., Tillamook County, C | | X | DATE: (Please Ch Condition Repo Not Found | | |
|---|--------------|--------------|--|--|--|
| • | | × | Condition Repo | | |
| • | | X | Not Found | ort Only | |
| | | Х | | | |
| | | X | | | |
| | | | Renewed | | |
| · · | | | Unrecorded | · | |
| | | | Surveyed In | | |
| Previous Rewitnesses, Restorations, Surveys, etc.: Rewitne | ss Book 7, P | | Referenced Ou | <u>ıt </u> | |
| Found Monument(s) and Accessories(Condition & Source): in an 8" diameter monument case in concrete prior to asphalt paving found to be as described on Tillamook County Survey Rewitness Boo | The found n | nonumer | Tillamook Cour nt is in good con | • | |
| Monument Set(Procedures & Description): The lid to the 8" diameter monument case was removed and the case was filled with concrete. The contractor was given permission to fill the monument case with asphalt by the Tillamook County Surveyor. A 2" diameter Tillamook County Brass Disk was placed at road surface. The 3" diameter brass disk which is now a subsurface monument is intact and in position. The 2" brass disk is stamped as shown hereon. Other New Accessories Set: No new accessories set. | | Sketch | ketch of Set Monument | | |
| | | | 1/4 | | |
| New Bearing Trees: No new bearing trees set. | | | | tila di chi di colta di colta di colta di | |
| Location & Comments: This monument is located at the centerline - centerline of Long Prairie Road and Schneidecker Lane at the Tillamook County Jail. | Surveyor | 's Stamp | REGISTER PROFESSI | ONAL | |
| Firm/Agency: Tillamook County Surveyor | | . | LAND SURV | The state of the s | |
| Address: 201 Laurel Avenue, Tillamook, Oregon 97141 | | | OREGO JIRY 41, 20 DANNY R. M | CNUTT | |
| Party Chief: Joe Jensen, Survey Supervisor | | | 49230 FENEWAL12-3 | ALL DESCRIPTION OF THE PARTY OF | |
| | | | | | |
| Notes: The monument as described in Rewitness Book 7, Page 90 was paved over during road construction. | Office Use C | Only | MOOK | CO | |