OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The Northeast Corner of Section 18	TOWNSHIP 2 South	RANGE 9 West		
COUNTY: Tillamook		DATE: 11-06-06		
	e section corner common to Section	s 7 8	T	(Please check one)
CORNER DESIGNATION: The section corner common to Sections 7, 8, 17 and 18, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.				Condition Report Only
		,,		Restoration
				Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Tillamook County Rewitness Card #372, Rewitness Book 6, Page 397. HLB OTAK, Inc. supplied the coordinate positions for the monuments set on map B-2296. See also Partition plat map P-95 and survey map A-3670. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Brass cap in a 10"				
diameter cast iron monument case stamped as shown in Rewitness Book 6, Page 397, This monument is now lying beneath the road surface.				
Monument Set (Procedures and Description): I set a 2" diameter		r	Sketch of Set Monument::	
	ss disk in concrete at road surface.		(T 2 S R 9 W S7 S8 S18 S17 2006
New accessories set: Set a nail and brass washer stamped "TC SURV" in the south face of a 6" x 6" gate post S 88° 36' 32" W 13.41'. Set a rock nail and brass washer stamped "TC SURV" in the asphalt N 01° 55' 17" W 95.12'. Found a 5/8" rebar stamped "HLB ASSOC. INC." in the East shoulder of Bewley Creek County Road N 01° 55' 17" W 716.04'.				
New Bearing Trees: No bearing trees were set.				
Location & Comments: This comer is located approximately 2' West of the as-built centerline of Bewley Creek County Road.				
Firm / Agency			S	URVEYOR'S SEAL
Address: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE			
Party Chief: Joe Jensen, PLS	60067, Survey Supervisor			REGISTERED PROFESSIONAL
Notes:				anns R. M. Nutt
Surveyor Surveyor			OREGON C. S.	
: .				DANNY R. MCNUTT 49230

