OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The Northwest	TOWNSHIP 1 North	RANGE 7 West		
corner of Section 4, T1N,				
R7W				
COUNTY: Tillamook DATE: 06-12-08				
CORNER DESIGNATION: The Center-South 1/16 corner of Section 4,				(Please check one)
T1N, R7W, W.M.,Tillamook County, Oregon.				Condition Report Only
				Restoration
			<u> </u>	Rewitness
				Unrecorded Report at surface
				Reset at surface
Devices Deviktores Besterations and Current stor Deviktores Dev				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Book 2, Page 289; Survey map B-337; Survey map F-40-145(copy of map B-337), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of Forestry cap				
upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the found				
monument. The cap is stamped as shown hereon. The Center-South 1/16 corner is located South 14° 42' 46" East 48.0				
feet (record values Map B-337) from the found reference monument. The position of the 1/16 corner falls in the road, so a				
monument was never set at the 1/16 corner position.				
Me accepted for and found the hearing trans described in Powitness Book 2. Dags 280 set by Louis M. Amort P.E. 2211				
We searched for and found the bearing trees described in Rewitness Book 2, Page 289 set by Louis W. Amort R.E. 2311 in 1953. These trees were set as accessories to the position of the actual Center-South 1/16 corner. We found a 6' tall, 36"				
diameter Douglas Fir stump at record position with visible scribe marks and a metal location poster tag. Found a very				
rotten, 4' tall, 60" diameter Douglas Fir stump at record position, with the '2311' scribe marks partially visible.				
	and Description: Not applicable.		Sket	ch of Found Monument:
•	• • • • • • • • • • • • • • • • • • • •	ł		
				Su.
			RM	
				•
CS 1/16				CS 1/16
1953				
2311				
New accessories set: Set a 72" hat section post 3 feet South of corner monument.				
New Bearing Trees: 31" diameter Douglas Fir tree scribed "CS 1/16 RM S4 BT" with nail and aluminum washer stamped				
"TILL.CO.SURVEYOR" set between the 'B&T', which bears North 04° West 12.5'. 12" diameter Douglas Fir tree scribed "CS 1/16 RM S4 BT" with nail and aluminum washer stamped				
"TILL.CO.SURVEYOR" set between the 'B&T', which bears South 52° East 29.2'.				
The angle right from the 31" Douglas Fir to the 12" Douglas Fir is 132° 00'00".				
	reference monument is located			
approximately 40' North of Nor	th Fork Road.			
Firm / Agency	novinda kana ya masa sa kata kata kata kata kata kata kat	, <u>, , , , , , , , , , , , , , , , , , </u>	5	SURVEYOR'S SEAL
Address: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE			
	Unication programming on the state of the st			
Party Chief: Joe Jensen, PLS	60067, Survey Supervisor		_	er distribution and the contract of the contra
	· ·			REGISTERED
N. C. A. C. W. C.				PROFESSIONAL
Notes:	ļ			LAND SURVEYOR
		_		anny R me nutt
Witnesses: Danny R. McNutt,	PLS 49230, Tillamook County	Č		and the same of th
Surveyor.	- 1			OREGON JULY 11, 2000
1.				DANNY R. MCNUTT
			1	49230
SOOK	Co.			RENEWAL12-31- 2008
AM	<u> </u>			

